

TriStar R+Y / G+Y LED


R+Y / G+Y Sequencing Troubleshooting Flowchart

v01



Abstract:

A flowchart to troubleshoot possible causes (and rectifications) of R+Y / G+Y LED sequencing with the TriStar (PWM) controller.



© 2013 Morningstar Corporation. All rights reserved.